## **Red Hand Classics**



Adres: Parallelweg 50, 5121 LD Rijen, NL. Tel: +31 (0)653225621

Used Antique Motorcycle Brief Evaluation Report		Dated: 31-10	-2023	Tester: Nick
Model: G9	Year: 1952 Reg No: ZM-51-60		51-60	Oils checked: OK
Colour: Black		Stock No:		CC: 500cc
VIN/Frame: 78447 Location: right s		ide under seat Engin		No: 52/G9.10227
Registration Documents: Dutch papers + documentation				
History: This motorcycle is imported from Canada before restoration by previous owner				
	Model: G9 Colour: Black Loca utch papers + docum	Model: G9 Year: 1952 Colour: Black Iocation: right side utch papers + documentation	Model: G9 Year: 1952 Reg No: ZM- Colour: Black Stock No: Location: right side under seat utch papers + documentation	Model: G9 Year: 1952 Reg No: ZM-51-60   Colour: Black Stock No:   Location: right side under seat Engine   utch papers + documentation Engine

Nice Average Poor COMMENTS Headlamp operation Х Switches are a little loose Х Switches are a little loose Rear lamp operation ELECTRONICS Stop lamp operation Х Horn operation X Charging system operation Х Battery Х Voltage: 6V Earth polarity: neg. Fuse: several Х Head bearings STEERING SUSPENSION Forks Х Х Swing arm bearings Wheel alignment X Girder links if applicable N/A Front brake Х BRAKES Rear brake Х Controls clevis pins etc. Х Brand/size: (see note 3 belew) Bridgestone motorcycle 3,00 x 19" DOT before Х Front tyre tread depth 2000 5,4mm Brand/size: (see note 3 below) Metzler segma 4,00 x 19" DOT before 2000 Rear tyre tread depth Х 6,4mm Front bearings Х WHEELS TYRES Rear bearings Х Front rim Х Painted: N/A Plating: Chrome Plating: chrome Painted: N/A Rear rim Х Front spokes Χ Х Rear spokes Exhaust silencers Х Plating: .% Comment: Х Exhaust pipes Plating: .% Comment: Fuel system leaks N/A Speedo X Reading: 1113 KM Cables Х Painted: N/A Handle bars/levers X Plating: Chrome Final drive chain Х GENERAL Primary chain tension Х Engine condition X Cold starting Х X Hot starting Oil leaks Х Small oil leak from engine Х Gearbox operation No of gears: 4 1 up N, 2, 3, 4 down Clutch operation Х Little clutch slip on full throttle Road test evaluation Х Distance covered: 15 KM Carburettor Х Type: Amal concentric 624 Test report:

Good running motorcycle with a high fun factor, they are very easy to start and ride around the countrylanes. The clutch is slipping a bit on full throttle and the tyres needs to be replaced.

notes:

- This report is only the opinion of the tester on the day and should only be considered as a rough guide as time does not permit an in depth report. 1. Antique machines will always require ongoing work.
- 2. All antique machines must be thoroughly checked over & fully serviced by a competent mechanic before any use, due to their age & the length of time that they may have been stored.
- 3. www.rospa.com recommends tyres that have been in storage for over 6 years or in use for 10 years should be replaced. For further information on tyre safety visit the ROSPA website page at https://www.rospa.com/Road-Safety/Resources/Free.aspx#motorcyclists/ or the Tyre Safe website at http://www.tyresafe.org/
- 4. The speedometer (if fitted) reading shown in this report is not necessarily an indication of the machines true mileage.
- We strongly recommend that all Flat tank motorcycles are run on ETHANOL FREE petrol, such as Aspen or Avgas. For other motorcycles run on E5 5. petrol or premium petrol.