Red Hand Classics



Adres: Parallelweg 50, 5121 LD Rijen, NL. Tel: +31 (0)653225621

Used Antique Motorcycle	n Report	Dated: 31-10-2023			Tester: Nick				
Make: Triumph	Model: 3TA			Year: 1967		Reg No: ZM-00-24		Oils checked: OK	
Price: Colour: C		Green / Grey		Ste	Stock No:		С	С: 350сс	
VIN/Frame: 3TA H 49504			Location: lef side headsto			stock	k Engine No: N/A military spare ei		N/A military spare engine
Registration Documents: Dutch papers									
History Old ov Dutch army motorsycle									

History: Old ex Dutch army motorcycle

		Nice	Average	Poor	COMMENTS
ELECTRONICS	Headlamp operation		Х		
	Rear lamp operation		X		
	Stop lamp operation		Х		
	Horn operation		X		
	Charging system operation	Х			
	Battery			Х	Voltage: 12V Earth polarity: pos. Fuse: 20 A
SUSPENSION	Head bearings	X			
	Forks	X			
	Swing arm bearings	X			
	Wheel alignment	X			
	Girder links if applicable				N/A
BRAKES	Front brake		Х		
	Rear brake		X		
	Controls clevis pins etc.	X			
WHEELS TYRES	Front tyre tread depth			X	Brand/size: Metzler ME77 3.5 x 18" DOT week 16 2012 4,0 mm
	Rear tyre tread depth			X	Brand/size: Yokohama Speedline II 110/90-18" DOT week 46 2001 0,8 mm
	Front bearings	Х			
	Rear bearings	Х		1	
	Front rim	Х			Plating: n/a Painted: black
	Rear rim	X			Plating: chrome or nickel and how good in %
	Front spokes	X			
	Rear spokes	X			
	Exhaust silencers		X		Plating: Chrome 80% Comment:
	Exhaust pipes		X		Plating: Chrome 70% Comment:
	Fuel system leaks		X		Little leak under carburettor
	Speedo		X		Reading: 13187 KM
	Cables	X			
	Handle bars/levers	X			Plating: Chrome 70 % Painted: N/A
F	Final drive chain	X			
GENERAL	Primary chain tension	X			
8	Engine condition		X		
	Cold starting	x			
	Hot starting	X			
	Oil leaks		X		Leak seal on gearbox clutch side.
	Gearbox operation	Х			No of gears: 4 1-N-2-3-4 first down the rest up
	Clutch operation	Х			
	Road test evaluation	Х			Distance covered: 15 KM
	Carburettor		Х		Type: Amal 375 / 35
Test rep	ort:				

Great motorcycle to ride thru the country lanes. This Triumph has a lot of torque with short gears so lots of fun to play with on the road. There is a small leak on the seal in the gearbox on the clutch side and the tyres needs to be replaced.

notes:

^{1.} This report is only the opinion of the tester on the day and should only be considered as a rough guide as time does not permit an in depth report. Antique machines will always require ongoing work.

^{2.} All antique machines must be thoroughly checked over & fully serviced by a competent mechanic before any use, due to their age & the length of time that they may have been stored.

www.rospa.com recommends tyres that have been in storage for over 6 years or in use for 10 years should be replaced. For further information on tyre safety visit the ROSPA website page at https://www.rospa.com/Road-Safety/Resources/Free.aspx#motorcyclists/ or the Tyre Safe website at https://www.rospa.com/Road-Safety/Resources/Free.aspx#motorcyclists/ or the Tyre Safe website at https://www.rospa.com/Road-Safety/Resources/Free.aspx#motorcyclists/ or the Tyre Safe website at http://www.tyresafe.org/

^{4.} The speedometer (if fitted) reading shown in this report is not necessarily an indication of the machines true mileage.

^{5.} We strongly recommend that all Flat tank motorcycles are run on ETHANOL FREE petrol, such as Aspen or Avgas. For other motorcycles run on E5 petrol or premium petrol.